

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/21/2016

Document Number:

685300988

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	205242	320854	St John, William (Cal)	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 900Name of Operator: ALAMOSA DRILLING INCAddress: 8150 N. CENTRAL EXPY - STE 750City: DALLAS State: TX Zip: 75205-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Martinez, Albert	(970) 264-2575	we5tgang@yahoo.com	pumper
Moore, Todd	(214) 368-6700/ (719)342-1445	kiowagas@sbcglobal.net	Owner

Compliance Summary:QtrQtr: NWNW Sec: 17 Twp: 32N Range: 1E

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/29/2015	674601819	SI	SI	SATISFACTORY	I		No
01/27/2015	674601399	SI	SI	ACTION REQUIRED	I		No
07/17/2013	668200524	SI	SI	ACTION REQUIRED	P		No
07/06/2011	200315676	PR	PR	SATISFACTORY			No
12/10/2010	200287485	PR	PR	ACTION REQUIRED			Yes
11/15/2010	200284808	PR	PR	ACTION REQUIRED			Yes
10/01/2010	200278941	PR	PR	ACTION REQUIRED			Yes
10/20/2009	200220541	PR	PR	SATISFACTORY			No
06/18/2009	200219434	PR	PR	SATISFACTORY			No
06/01/2006	200091101	PR	PR	SATISFACTORY		Pass	No
05/22/2003	200040739	PR	PR	SATISFACTORY		Pass	No
06/24/1999	500135035	ID	TA			Fail	Yes
03/04/1999	500135034	PR	PR			Pass	No
06/30/1997	500135033	PR	PR			Pass	No

Inspector Comment:

This report contains corrective actions and comments. See Lease Road, Good Housekeeping, Facilities, and Facility Section of report for additional details. See link at end of report for path to downloadable pictures.

Related Facilities:

Inspector Name: St John, William (Cal)

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
205242	WELL	PR	04/01/2015	OW	007-06120	CHAVEZ 1	SI	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	ACTION REQUIRED	Lease Road needs maintenance.	Maintain and repair access road per Rule 604.c.(2).S	08/31/2016

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
UNUSED EQUIPMENT	ACTION REQUIRED	Sections of pipe and section of sucker rod lying on the ground on location.	Remove pipe and sucker rod to comply with Rule 603.f using the Rule 603.f guidance document for further details.	08/31/2016
WEEDS	ACTION REQUIRED	Weeds and grass are covering production area and growing around production equipment.	Remove weeds and grass and implement weed control program to comply with Rule 603.f using the Rule 603.f guidance document for further details.	08/11/2016
OTHER	ACTION REQUIRED	Stained soil outside wellhead fencing and on the ground around wellhead.	Clean up and remediate stained soil per Rule 906.a.	08/31/2016

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	Post and Hog Wire.		

Equipment:				
Type: Pump Jack	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment				
Corrective Action		Date:		
Type: Ancillary equipment	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment Wellhead				
Corrective Action		Date:		
Type: Prime Mover	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment Electric Motor				
Corrective Action		Date:		
Type: Flow Line	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment				
Corrective Action		Date:		
Type: Other	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment Metal Equipment Building				
Corrective Action		Date:		
Type: Ancillary equipment	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment Electric Service Equipment				
Corrective Action		Date:		

Facilities:				
<input type="checkbox"/> New Tank		Tank ID: _____		
Contents	#	Capacity	Type	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST	,
S/AR	SATISFACTORY	Comment:		
Corrective Action:		Corrective Date:		

Paint	
Condition	Adequate
Other (Content) _____	
Other (Capacity) _____	
Other (Type) _____	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Corrective Action	Remove weed and grass and repair berms or place in other secondary containment device to comply with Rule 605.a.(4).			Corrective Date 08/31/2016
Comment	Weeds and grass are growing inside and on containment berms.			

Venting:				
-----------------	--	--	--	--

Inspector Name: St John, William (Cal)

Yes/No	NO
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 205242

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 205242 Type: WELL API Number: 007-06120 Status: PR Insp. Status: SI

Idle WellPurpose: ☒ Shut In☐ Temporarily Abandoned

Reminder: _____

S/A/V: _____

CA Date: **08/31/2016**CA: **Update monthly report of operations per Rule 309.**Comment: **Production records show last production was April 2015 and well SI from May 2015 to December 2015. No production reported since December 2015.****Environmental****Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

Inspector Name: St John, William (Cal)

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

S/A/V: SATISFACTOR _____ Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

Inspector Name: St John, William (Cal)

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685301014	Weeds and grass at Pump Jack and sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3916853
685301015	Stained soil outside fencing	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3916854
685301016	Pipe and sucker rod	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3916855
685301017	Weeds and grass at tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3916856
685301018	Location access road view	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3916857
685301019	Stained soil at wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3916858