

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/21/2016

Document Number:

685300990

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	205262	320864	St John, William (Cal)	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 900Name of Operator: ALAMOSA DRILLING INCAddress: 8150 N. CENTRAL EXPY - STE 750City: DALLAS State: TX Zip: 75205-☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED☒ INSPECTOR REQUESTS FORM 42 WHEN
CORRECTIVE ACTIONS ARE COMPLETED**Contact Information:**

Contact Name	Phone	Email	Comment
Martinez, Albert	(970) 264-2575	we5tgang@yahoo.com	pumper
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Moore, Todd	(214) 368-6700/ (719)342-1445	kiowagas@sbcglobal.net	Owner

Compliance Summary:QtrQtr: NENE Sec: 18 Twp: 32N Range: 1E

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/29/2015	674601817	PR	PR	SATISFACTORY	I		No
01/27/2015	674601401	PR	PR	ACTION REQUIRED	I		No
07/17/2013	668200528	PR	SI	ACTION REQUIRED	P		No
07/05/2011	200315681	PR	PR	SATISFACTORY			No
04/17/2011	200308920	PR	SI	ACTION REQUIRED			Yes
12/10/2010	200287483	PR	PR	ACTION REQUIRED			Yes
11/15/2010	200284811	PR	PR	ACTION REQUIRED			Yes
10/01/2010	200278629	PR	SI	ACTION REQUIRED			Yes
10/20/2009	200220490	PR	TA	ACTION REQUIRED			Yes
09/24/2009	200219603	ES	SI	ACTION REQUIRED			Yes
06/18/2009	200219427	ID	SI	ACTION REQUIRED			Yes
06/01/2006	200091142	PR	PR	ACTION REQUIRED		Fail	Yes
02/13/2004	200049898	PR	PR	SATISFACTORY		Pass	No
05/22/2003	200049897	PR	PR	ACTION REQUIRED		Pass	No
07/06/2000	200008339	PR	PR	ACTION REQUIRED		Fail	Yes
06/24/1999	500135046	CO	WO			Fail	Yes
03/04/1999	500135045	ID	TA			Pass	No

Inspector Comment:

Inspector Name: St John, William (Cal)

This inspection report contains corrective actions and comments. See Signs/Marker, Facilities, and Facility Sections of report for additional details. See link at end of report for path to downloadable pictures.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
205262	WELL	PR	03/21/2011	OW	007-06141	NIELSEN 5	PR	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY			
WELLHEAD	ACTION REQUIRED	Sign at wellhead is faded and nearly unreadable and needs to be replaced.	Install sign to comply with rule 210.	09/30/2016

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	Post and Hog Wire		

Equipment:

Type: Prime Mover	# 1	Satisfactory/Action Required: SATISFACTORY
-------------------	-----	--

Comment		Electric Motor	
Corrective Action		Date:	
Type: Pump Jack	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action		Date:	
Type: Ancillary equipment	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment		Wellhead	
Corrective Action		Date:	
Type: Ancillary equipment	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment		Electrical Service Equipment	
Corrective Action		Date:	
Type: Flow Line	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action		Date:	

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST	,

S/AR	SATISFACTORY	Comment:	
Corrective Action:		Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate

Corrective Action	Remove weeds and grass and repair berms or place in other secondary containment device to comply with Rule 605.a.(4)	Corrective Date	08/31/2016
Comment	Weeds and grass are growing inside and on containment berms.		

Venting:

Yes/No	NO
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 205262

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 205262 Type: WELL API Number: 007-06141 Status: PR Insp. Status: PR

Producing Well

Comment: Production records indicate last reported production was December 2015.

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____

Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____

CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____

CA Date _____

Guy line anchors marked? _____

CM _____

CA _____

CA Date _____

1003b. Area no longer in use? _____

Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____

Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Inspector Name: St John, William (Cal)

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

S/A/V: SATISFACTOR _____ Corrective Date: _____
Y _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685301023	Weeds and grass at tank staircase	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3916862
685301024	Wellhead sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3916863
685301025	Weeds and grass at tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3916864