



Photo 1. View of the project area from the southwestern corner of the well pad facing center.



Photo 2. View of the western portion of the well pad from the southwestern corner facing northward. Revegetation in this area is largely intermediate wheatgrass (*Thinopyron intermedium*) and crested wheatgrass (*Agropyron cristatum*).





Photo 3. View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 4. View of what appears to be surface owner equipment stored on the well pad.





Photo 5. View of unused equipment and debris stored on the well pad.



Photo 6. View of cobble run-down in northwestern corner that appears to be functional.





Photo 7. View of the eastern portion of the project area from the northeastern corner facing southward.