

Final Reclamation Inspection- Sandau #1 Spread Field



Photo 1. Photo taken from the central irrigation pivot, facing Northwest. Uniform vegetative crop growth throughout location.

Final Reclamation Inspection- Sandau #1 Spread Field



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo 2. Photo taken from the central irrigation pivot, facing West. Uniform vegetative crop growth throughout location.

Final Reclamation Inspection- Sandau #1 Spread Field



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo 3. Photo taken from the central irrigation pivot, facing Southwest. Uniform vegetative crop growth throughout location.