



Photo 1. View from the approximate wellhead location facing northward. Location is on a low terrace above Navajo Creek. Vegetation observed includes smooth brome (*Bromus inermis*), willows (*Salix* sp.), and cottonwoods (*Populus* sp.).



Photo 2. View from the approximate wellhead location facing eastward.



Photo 3. Birdseye view of cable that could be a piece of rig cable. No other evidence of equipment or oil and gas operations was observed.