

Final Reclamation Inspection



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo 1. Photo taken from the eastern tank battery location, facing North. High density of Kochia sp. along the perimeter of the location.

Final Reclamation Inspection



Photo 2. Photo taken from the well location, facing West. Only one Scotch thistle plant currently at location.