

# Final Reclamation Inspection



**Photo 1.** Photo taken from wellhead location, facing West. Kochia sp. observed throughout location.

# Final Reclamation Inspection



**Photo 2.** Photo taken north of well location, facing North. Kochia sp. observed throughout location.

# Final Reclamation Inspection



**Photo 3.** Photo taken south of well location, facing South. Kochia sp. observed throughout location.