

# Final Reclamation Inspection



**Photo 1.** Photo taken from northern well location, facing North. Scotch thistle observed throughout perimeter of location.

# Final Reclamation Inspection



**Photo 2.** Close up photo taken north of well location. Scotch thistle observed at high densities as shown with this photo.

# Final Reclamation Inspection



**Photo 3.** Photo taken from eastern well location, facing South. Scotch thistle observed throughout perimeter of location.