

Final Reclamation Inspection- Bond Release



Photo 1. Photo taken from North of location, facing Southeast. Does not appear the well was constructed at the proposed location based off field observations and aerial imagery.

Final Reclamation Inspection- Bond Release



Photo 2. Photo taken from North of location, facing South. Does not appear the well was constructed at the proposed location based off field observations and aerial imagery.

Final Reclamation Inspection- Bond Release



Photo 3. Photo taken from North of location, facing Southwest. Does not appear the well was constructed at the proposed location based off field observations and aerial imagery.

Final Reclamation Inspection- Bond Release



Photo 4. 2015 aerial imagery using COGCC GISOnline. It appears the location was never built based off aerial imagery and field observations.