

Final Reclamation Inspection



Photo 1. Photo taken from center of location. Vegetative crop growth appeared to be shorter than reference areas; however, crop height at location was above 80% of crop height at reference areas.