

Final Reclamation Inspection

06/28/2016

Operator: Petro-Canada

Location ID: 311698

Adams County, CO

NESW Section 13 T3S R59W

Aaron Trujillo

Reclamation Specialist

COGCC



Image U.S. Geological Survey

Google earth

1993

Imagery Date: 9/3/1993 lat 39.788893° lon -103.937537° elev 5116 ft eye alt 6969 ft

Figure 1: 1993 aerial imagery showing where location exists vs. scout card records.



Figure 2: Most recent aerial imagery (2013) shows approximate outline of degradation within drainage. Approximate area of degradation is 1.3 acres.



Figure 3: Photo taken from the north side of the intermittent stream, facing east. Photo shows vegetation within the drainage upstream of location.



Figure 4: Photo taken from the north side of the intermittent stream, facing southeast towards the location (south side of stream). Photo shows vegetation within the drainage. Note degradation within drainage becomes evident.



Figure 5: Photo taken from the north side of the intermittent stream, facing south towards the location (south side of stream). Photo shows vegetation within the drainage. Note degradation within drainage becomes evident.



Figure 6: Photo taken from the north side of the intermittent stream, facing southwest. Photo shows (lack of) vegetation within the drainage downstream of location.



Figure 7: Photo taken within drainage, adjacent to the pit location, facing east. Photo shows areas of degradation.



Figure 8: Photo taken within intermittent stream, facing west. Photo shows degradation within stream. 6' measuring stick in photo used for reference.