

Final Reclamation Inspection

08/05/2016

Operator: Diversified Operating Corp.

Location ID: 408068

Weld County, CO

SESW Section 31 T8N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Figure 2: Photo of the starting point for the disturbance transect, facing west.



Figure 3: Photo of vegetation at the 50th point of the disturbance transect, facing south.



Figure 4: Photo of vegetation at the 50th point of the disturbance transect, facing north.



Figure 5: Photo of vegetation at the 50th point of the disturbance transect.



Figure 6: Photo of the end point for the disturbance transect, facing east.



Figure 7: Photo of the starting point for the reference transect, facing east



Figure 8: Photo of vegetation at the 50th point of the reference transect, facing north.



Figure 9: Photo of vegetation at the 50th point of the reference transect, facing south.



Figure 10: Photo of vegetation at the 50th point of the reference transect.




Figure 11: Photo of the end point for the reference transect, facing west.



Figure 12: Red/Discolored soil found on location.