

Final Reclamation Inspection

08/05/2016

Operator: Diversified Operating Co

Location ID: 408067

Weld County, CO

NENW Section 6 T7N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Figure 1: Photo of bare area found at location. Photo shows vegetation, though scarce, is growing through areas where gravel remains.



Figure 2: Photo taken from location, facing north. Photo of vegetation over the reclamation area.



Figure 3: Photo taken from location, facing east. Photo of vegetation over the reclamation area.



Figure 4: Photo taken from location, facing south. Photo of vegetation over the reclamation area.



08.05.2016 14:21

Figure 5: Photo taken from location, facing west. Photo of vegetation over the reclamation area.