



Photo#1: There is no evidence of the DA Well on this Active Location.

August 1, 2016

Inspection Photos: Exxon Mobil DA Love Ranch 103-10514



Photo#2: There is no evidence of the DA Well on this Active Location.

Inspection Photos: Exxon Mobil DA Love Ranch 103-10514

August 1, 2016