

Final Reclamation Inspection



Photo 1. Photo taken from approximate center of location, facing West. Location appears to be reflective of reference areas, even though the surrounding area and location have undesirable plant species. Also, prairie dogs occupy the surrounding area which is also affecting vegetative growth.

Final Reclamation Inspection



Photo 2. Photo taken from approximate center of location, facing East. Location appears to be reflective of reference areas, even though the surrounding area and location have undesirable plant species. Also, prairie dogs occupy the surrounding area which is also affecting vegetative growth.

Final Reclamation Inspection



Photo 3. Photo taken from approximate center of location, facing South. Location appears to be reflective of reference areas, even though the surrounding area and location have undesirable plant species. Also, prairie dogs occupy the surrounding area which is also affecting vegetative growth.

Final Reclamation Inspection



Photo 4. Photo taken southeast of location, facing East. Photo of an a Prairie dog colony.