

# Reclamation Inspection

08/15/2016

Operator: Diversified Operating Corp

Location ID: 408223

Weld County, CO

SESW Section 21 T8N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Department of Natural Resources



**Figure 1:** Photo of the starting point for the disturbance transect, facing southeast.





**Figure 2:** Photo of the 50<sup>th</sup> point of the disturbance transect, facing southwest.





**Figure 3:** Photo of the 50<sup>th</sup> point of the disturbance transect, facing northeast.





**Figure 4:** Photo of the 50<sup>th</sup> point of the disturbance transect.





**Figure 5:** Photo of the end point for the disturbance transect, facing northwest.





**Figure 6:** Photo of the starting point for the reference transect, facing north.





**Figure 7:** Photo of the 50<sup>th</sup> point of the reference transect, facing east.





**Figure 8:** to of the 50<sup>th</sup> point of the reference transect, facing west.





**Figure 9:** Photo of the 50<sup>th</sup> point of the reference transect.





**Figure 10:** Photo of the end point for the reference transect, facing south.