

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/18/2016

Document Number:

685301136

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	214267	325204	St John, William (Cal)	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 96705Name of Operator: WPX ENERGY PRODUCTION LLCAddress: P O BOX 3102 MS-25-2City: TULSA State: OK Zip: 74101

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Inspection, WPX	970-263-2716	COGCCInspectionReportsSanJuan@wpxenergy.com	WPX Inspection Mailbox

Compliance Summary:QtrQtr: SESE Sec: 3 Twp: 33N Range: 10W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/10/2012	661700253	PR	PR	SATISFACTORY	Pass		No
10/26/2010	200284359	PR	SI	ACTION REQUIRED			Yes
06/01/2010	200252769	PR	PR	SATISFACTORY			No
03/16/2009	200205900	PR	PR	SATISFACTORY			No
01/25/2007	200108072	PR	PR	SATISFACTORY		Pass	No
11/09/2005	200085402	PR	PR	SATISFACTORY		Pass	No
04/20/2004	200053664	PR	PR	SATISFACTORY		Pass	No
09/17/2003	200044769	PR	PR	SATISFACTORY		Pass	No
11/14/2001	200021993	PR	PR	SATISFACTORY		Pass	No
10/05/2000	200010923	PR	PR	SATISFACTORY		Pass	No
06/28/1999	500147117	PR	PR			Pass	No
11/20/1997	500147116	PR	PR			Pass	No
02/06/1996	500147115	PR	PR			Pass	Yes
09/22/1994	500147114	PR	PR			Pass	No

Inspector Comment:

This report contains corrective actions and comments. See Good Housekeeping Section of report for additional details. See link at end of report for path to downloadable pictures.

Related Facilities:

Inspector Name: St John, William (Cal)

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
214267	WELL	PR	03/15/2007	GW	067-05601	BONDAD 33-10 4	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
UNUSED EQUIPMENT	ACTION REQUIRED	There are four concrete barriers on location behind meter run and separator that may of come from edge of road. They do not appear to be in use.	Remove concrete barriers to comply with Rule 603.f using the Rule 603.f guidance document for further details.	09/21/2016
WEEDS	ACTION REQUIRED	Weeds are growing in production area and along E and S perimeter.	Remove weeds to comply with Rule 603.f using the Rule 603.f guidance document for further details.	08/31/2016

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK BATTERY	SATISFACTORY	Post and Hog Wire		

Equipment:			
Type: Flow Line	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action		Date:	
Type: Deadman # & Marked	# 4	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action		Date:	
Type: Bird Protectors	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action		Date:	
Type: Ancillary equipment	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment		Telemetry Equipment	
Corrective Action		Date:	
Type: Other	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment		Cathodic Protection Equipment	
Corrective Action		Date:	
Type: Ancillary equipment	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment		Wellhead	
Corrective Action		Date:	
Type: Gas Meter Run	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action		Date:	
Type: Horizontal Heated Separator	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action		Date:	

Tanks and Berms:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	OTHER	Open Top	,
S/AR	SATISFACTORY	Comment: Chicken wire covering top of tank.		
Corrective Action:				Corrective Date:
Paint				
Condition	Adequate			
Other (Content) _____				
Other (Capacity) 55 BBLs				
Other (Type) _____				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Inspector Name: St John, William (Cal)

Corrective Action		Corrective Date	
Comment			

Venting:

Yes/No	NO
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 214267

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID:	214267	Type:	WELL	API Number:	067-05601	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: **PR****Environmental****Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Inspector Name: St John, William (Cal)

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

S/A/V: SATISFACTORY Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685301136	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3932797
685301153	Weeds by meter run	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3932779
685301154	Weeds along perimeter	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3932780
685301155	Concrete Barriers	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3932781