

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2016

Document Number:

673403543

Overall Inspection:

SATISFACTORY w/ CMT
or AR**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection
	222309	312771	Waldron, Emily	<input type="checkbox"/> 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10428Name of Operator: DIVERSIFIED ENERGY LLCAddress: 10940 S PARKER ROADCity: PARKER State: CO Zip: 80134

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Haack, Jason	303-995-0826	jhaack@oagproduction.com	
Ikenouye, Teri		teri.ikenouye@state.co.us	

Compliance Summary:QtrQtr: NWSW Sec: 13 Twp: 5N Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/02/2015	673402427	PR	SI	ACTION REQUIRED			No
07/20/2015	673402259	PR	PR	ACTION REQUIRED			No
01/27/2014	673400225	PR	PR	ACTION REQUIRED	Fail		No
11/19/2013	673400123	PR	PR	ACTION REQUIRED	Fail		No
05/10/2012	668500044	PR	TA	ALLEGED VIOLATION	In Process		Yes
06/27/2011	200323461	PR	SI	ACTION REQUIRED			Yes
10/03/2006	200103242	ID	SI	SATISFACTORY		Pass	No
02/22/1999	500154448	ID	SI			Pass	No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
116613	PIT		09/23/1999		-	A.P. URIE	<input type="checkbox"/>
222309	WELL	PR	11/01/2014	OW	081-05284	A.P. URIE 1	SI <input checked="" type="checkbox"/>
442574	SPILL OR RELEASE	CL	07/21/2015		-	SPILL/RELEASE POINT	CL <input type="checkbox"/>

Equipment:Location Inventory

Inspector Name: Waldron, Emily

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WEEDS	ACTION REQUIRED	Noxious weeds on location. Noxious and annual weeds within 25 feet of wellhead.	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	09/05/2016

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Equipment:

Type: Pump Jack	# 1	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action	Date:	
Type: Deadman # & Marked	#	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action	Date:	

Venting:

Yes/No	NO
Comment	

Flaring:

Type	Satisfactory/Action Required
Comment:	
Corrective Action:	Correct Action Date:

Predrill

Location ID: 222309

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 222309 Type: WELL API Number: 081-05284 Status: PR Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDS

S/A/V: _____ CA Date: _____

CA: **Contact COGCC production staff to submit Monthly Operations Report to comply with rule 309.**Comment: **No production reported since May 2015.****Environmental****Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Date: _____

Inspector Name: Waldron, Emily

Corrective Action: _____		
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____		Depth to Ground Water: _____
<u>Water Well:</u>		
DWR Receipt Num: _____	Owner Name: _____	GPS : _____
<u>Field Parameters:</u>		
Sample Location: _____		
Emission Control Burner (ECB): _____		
Comment: _____		
Pilot: _____	Wildlife Protection Devices (fired vessels): _____	
<u>Reclamation - Storm Water - Pit</u>		
<u>Interim Reclamation:</u>		
Date Interim Reclamation Started: _____		Date Interim Reclamation Completed: _____
Land Use: _____		
Comment: _____		
1003a. Waste and Debris removed? _____		
CM _____		
CA _____		CA Date _____
Unused or unneeded equipment onsite? _____		
CM _____		
CA _____		CA Date _____
Pit, cellars, rat holes and other bores closed? _____		
CM _____		
CA _____		CA Date _____
Guy line anchors marked? _____		
CM _____		
CA _____		CA Date _____
1003b. Area no longer in use? _____		Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____		
1003d. Drilling pit closed? _____		Subsidence over on drill pit? _____
Cuttings management: _____		
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____		
Production areas have been stabilized? _____		Segregated soils have been replaced? _____
RESTORATION AND REVEGETATION		
<u>Cropland</u>		
Top soil replaced _____	Recontoured _____	Perennial forage re-established _____
<u>Non-Cropland</u>		

Inspector Name: Waldron, Emily

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: SATISFACTORY Corrective Date: _____

Comment: No apparent soil migration; erosion or soil movement.

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Follow up to inspection from 9/2/2015 document number 673402427. Tank mentioned in previous inspections has been removed. Berm has been leveled. No stormwater BMPs were observed during this inspection, but no soil migration was observed. This report is Action Required due to weeds and the need to submit monthly operations reports.	waldron	08/24/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673403543	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3936734
673403547	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3936730