

Fuqua 19-02-10-1H

Inspection# 673403582

1 of 3 tanks labeled as both produced water and crude oil. Previous operator contact information on all tanks.



2 unlabeled tanks.



Equipment stored on location.



Flaring out of field flare stack.

