



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is progressing and with desirable and weedy species such as western wheatgrass (*Pascopyrum smithii*), rubber rabbitbrush (*Chrysothamnus nauseosus*), and cheatgrass (*Bromus tectorum*).



Photo 3. View of the eastern portion of the project area from the southeastern corner facing northward.



Photo 3. View of the Russian knapweed (*Acroptilon repens*) in the eastern portion of the project area. Approximately 200 plants were observed.



Photo 3. View of salt cedar (*Tamarix* sp.) growing in silt trap in southeastern portion of the project area.



Photo 3. View of musk thistles (*Carduus nutans*) growing within the southern portion of the interim reclamation area. At least 1000 musk thistles are growing throughout the reclamation areas.



Photo 3. View of the project area from the northeastern edge facing westward. Revegetation is progressing with western wheatgrass (*Pascopyrum smithii*) and smooth brome (*Bromus inermis*). Vegetation is still sparse in many areas.