

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/15/2016

Submitted Date:

09/15/2016

Document Number:

674703127**FIELD INSPECTION FORM**

Loc ID 335798	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED																																																																																																																																															
2A Doc Num: _____			Findings: 21 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																																																																																																															
Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>																																																																																																																																																		
Contact Information: <table border="1" style="width:100%"> <thead> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> </thead> <tbody> <tr> <td>Elsener, Garrett</td> <td></td> <td>garrett@caerusoilandgas.com</td> <td></td> </tr> <tr> <td>McKee, Michael</td> <td></td> <td>MMckee@caerusoilandgas.com</td> <td></td> </tr> <tr> <td>Janicek, Jake</td> <td></td> <td>JJanicek@caerusoilandgas.com</td> <td></td> </tr> </tbody> </table>				Contact Name	Phone	Email	Comment	Elsener, Garrett		garrett@caerusoilandgas.com		McKee, Michael		MMckee@caerusoilandgas.com		Janicek, Jake		JJanicek@caerusoilandgas.com																																																																																																																																
Contact Name	Phone	Email		Comment																																																																																																																																														
Elsener, Garrett		garrett@caerusoilandgas.com																																																																																																																																																
McKee, Michael		MMckee@caerusoilandgas.com																																																																																																																																																
Janicek, Jake		JJanicek@caerusoilandgas.com																																																																																																																																																
Inspected Facilities: <table border="1" style="width:100%"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>265451</td><td>WELL</td><td>PR</td><td>07/31/2009</td><td>GW</td><td>045-09020</td><td>CHEVRON 22-7D</td><td>PR</td></tr> <tr><td>265452</td><td>WELL</td><td>PR</td><td>08/31/2009</td><td>GW</td><td>045-09019</td><td>CHEVRON 23-7D</td><td>PR</td></tr> <tr><td>265453</td><td>WELL</td><td>PR</td><td>03/31/2011</td><td>GW</td><td>045-09016</td><td>CHEVRON 12-7D</td><td>PR</td></tr> <tr><td>265454</td><td>WELL</td><td>PR</td><td>07/31/2009</td><td>GW</td><td>045-09018</td><td>CHEVRON 13-7D</td><td>PR</td></tr> <tr><td>265455</td><td>WELL</td><td>PR</td><td>03/31/2010</td><td>GW</td><td>045-09017</td><td>CHEVRON 14-7D</td><td>PR</td></tr> <tr><td>265456</td><td>WELL</td><td>PR</td><td>03/31/2010</td><td>GW</td><td>045-09021</td><td>CHEVRON 24-7D</td><td>PR</td></tr> <tr><td>291053</td><td>WELL</td><td>PR</td><td>08/01/2010</td><td>GW</td><td>045-14269</td><td>CHEVRON-MARATHON 12C-7D</td><td>PR</td></tr> <tr><td>291054</td><td>WELL</td><td>PR</td><td>09/01/2010</td><td>GW</td><td>045-14270</td><td>Chevron 12D-7D</td><td>PR</td></tr> <tr><td>291055</td><td>WELL</td><td>PR</td><td>08/01/2009</td><td>GW</td><td>045-14271</td><td>CHEVRON 13A-7D</td><td>PR</td></tr> <tr><td>291056</td><td>WELL</td><td>PR</td><td>03/31/2011</td><td>GW</td><td>045-14272</td><td>Chevron 13C-7D</td><td>PR</td></tr> <tr><td>291057</td><td>WELL</td><td>PR</td><td>09/01/2010</td><td>GW</td><td>045-14273</td><td>Chevron 13D-7D</td><td>PR</td></tr> <tr><td>291058</td><td>WELL</td><td>PR</td><td>09/01/2010</td><td>GW</td><td>045-14274</td><td>Chevron 14A-7D</td><td>PR</td></tr> <tr><td>291059</td><td>WELL</td><td>PR</td><td>10/01/2011</td><td>GW</td><td>045-14275</td><td>CHEVRON 23D-7D</td><td>PR</td></tr> <tr><td>291060</td><td>WELL</td><td>PR</td><td>10/01/2011</td><td>GW</td><td>045-14276</td><td>Chevron 12A-7D</td><td>PR</td></tr> <tr><td>291061</td><td>WELL</td><td>PR</td><td>10/01/2011</td><td>GW</td><td>045-14277</td><td>Chevron 11D-7D</td><td>PR</td></tr> <tr><td>291075</td><td>WELL</td><td>PR</td><td>09/01/2010</td><td>GW</td><td>045-14291</td><td>Chevron 24B-7D</td><td>PR</td></tr> <tr><td>291076</td><td>WELL</td><td>PR</td><td>03/31/2011</td><td>GW</td><td>045-14292</td><td>Chevron 24A-7D</td><td>PR</td></tr> </tbody> </table>			Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	265451	WELL	PR	07/31/2009	GW	045-09020	CHEVRON 22-7D	PR	265452	WELL	PR	08/31/2009	GW	045-09019	CHEVRON 23-7D	PR	265453	WELL	PR	03/31/2011	GW	045-09016	CHEVRON 12-7D	PR	265454	WELL	PR	07/31/2009	GW	045-09018	CHEVRON 13-7D	PR	265455	WELL	PR	03/31/2010	GW	045-09017	CHEVRON 14-7D	PR	265456	WELL	PR	03/31/2010	GW	045-09021	CHEVRON 24-7D	PR	291053	WELL	PR	08/01/2010	GW	045-14269	CHEVRON-MARATHON 12C-7D	PR	291054	WELL	PR	09/01/2010	GW	045-14270	Chevron 12D-7D	PR	291055	WELL	PR	08/01/2009	GW	045-14271	CHEVRON 13A-7D	PR	291056	WELL	PR	03/31/2011	GW	045-14272	Chevron 13C-7D	PR	291057	WELL	PR	09/01/2010	GW	045-14273	Chevron 13D-7D	PR	291058	WELL	PR	09/01/2010	GW	045-14274	Chevron 14A-7D	PR	291059	WELL	PR	10/01/2011	GW	045-14275	CHEVRON 23D-7D	PR	291060	WELL	PR	10/01/2011	GW	045-14276	Chevron 12A-7D	PR	291061	WELL	PR	10/01/2011	GW	045-14277	Chevron 11D-7D	PR	291075	WELL	PR	09/01/2010	GW	045-14291	Chevron 24B-7D	PR	291076	WELL	PR	03/31/2011	GW	045-14292	Chevron 24A-7D	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																																											
265451	WELL	PR	07/31/2009	GW	045-09020	CHEVRON 22-7D	PR																																																																																																																																											
265452	WELL	PR	08/31/2009	GW	045-09019	CHEVRON 23-7D	PR																																																																																																																																											
265453	WELL	PR	03/31/2011	GW	045-09016	CHEVRON 12-7D	PR																																																																																																																																											
265454	WELL	PR	07/31/2009	GW	045-09018	CHEVRON 13-7D	PR																																																																																																																																											
265455	WELL	PR	03/31/2010	GW	045-09017	CHEVRON 14-7D	PR																																																																																																																																											
265456	WELL	PR	03/31/2010	GW	045-09021	CHEVRON 24-7D	PR																																																																																																																																											
291053	WELL	PR	08/01/2010	GW	045-14269	CHEVRON-MARATHON 12C-7D	PR																																																																																																																																											
291054	WELL	PR	09/01/2010	GW	045-14270	Chevron 12D-7D	PR																																																																																																																																											
291055	WELL	PR	08/01/2009	GW	045-14271	CHEVRON 13A-7D	PR																																																																																																																																											
291056	WELL	PR	03/31/2011	GW	045-14272	Chevron 13C-7D	PR																																																																																																																																											
291057	WELL	PR	09/01/2010	GW	045-14273	Chevron 13D-7D	PR																																																																																																																																											
291058	WELL	PR	09/01/2010	GW	045-14274	Chevron 14A-7D	PR																																																																																																																																											
291059	WELL	PR	10/01/2011	GW	045-14275	CHEVRON 23D-7D	PR																																																																																																																																											
291060	WELL	PR	10/01/2011	GW	045-14276	Chevron 12A-7D	PR																																																																																																																																											
291061	WELL	PR	10/01/2011	GW	045-14277	Chevron 11D-7D	PR																																																																																																																																											
291075	WELL	PR	09/01/2010	GW	045-14291	Chevron 24B-7D	PR																																																																																																																																											
291076	WELL	PR	03/31/2011	GW	045-14292	Chevron 24A-7D	PR																																																																																																																																											

General Comment: Follow up to 05/03/2016 inspection doc # 674702670 Corrective action have been made. Unneeded electric line behind chemical containers at the tank battery needs to be removed from location.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 866-580-9382

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unneeded electric line behind chemical containers at the tank battery needs to be removed from location.		
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	#		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	#		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Chemical containers at wells and tank battery.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	#		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS	
CONDENSATE	1	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS	
PRODUCED WATER	1	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Inspected Facilities									
Facility ID:	265451	Type:	WELL	API Number:	045-09020	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	265452	Type:	WELL	API Number:	045-09019	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	265453	Type:	WELL	API Number:	045-09016	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	265454	Type:	WELL	API Number:	045-09018	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	265455	Type:	WELL	API Number:	045-09017	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	265456	Type:	WELL	API Number:	045-09021	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291053	Type:	WELL	API Number:	045-14269	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291054	Type:	WELL	API Number:	045-14270	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	291055	Type:	WELL	API Number:	045-14271	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291056	Type:	WELL	API Number:	045-14272	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291057	Type:	WELL	API Number:	045-14273	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291058	Type:	WELL	API Number:	045-14274	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291059	Type:	WELL	API Number:	045-14275	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291060	Type:	WELL	API Number:	045-14276	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291061	Type:	WELL	API Number:	045-14277	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	291075	Type:	WELL	API Number:	045-14291	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	291076	Type:	WELL	API Number:	045-14292	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	
		Culverts	Pass			
		Compaction	Pass			
		Ditches	Pass			
Seeding	Pass					
		Check Dams	Pass			
Gravel	Pass					
Compaction	Pass					
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674703127	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3952283