

On September 2, 2016 COGCC Environmental Field Inspection of DIVERSIFIED ENERGY LLC
(Diversified) Urie #1 Location ID: 312771.



Location sign.



Well head and pumpjack.



Valve locked out.



Electrical locked out.



5-gal pail overflowing.



Looking north from well to former tank battery location.



Looking east along former tank battery location.



Looking east along former tank battery location



Valves/risers.



Valves/risers.



Tank battery area, concrete pads looking east.



Tank battery area, concrete pads looking west.



View looking toward Weise and Urie #2 Locations. Apparent pipelng markers perpendicular to pipe on ground.



View looking toward Weise and Urie #2 Locations.



Pipeline along east of Location going uphill (North) toward Weise and Urie #2 Locations.



of photo on bench.

Location. Former tank battery production area to left