



Photo#1: Overview of Location from Entry to North

September 5, 2016

Inspection Photos: Laramie Buzzard Creek Loc#311747



Photo#2: Location footprint has not been reduced.

Inspection Photos: Laramie Buzzard Creek Loc#311747

September 5, 2016





Photo#3: Location has not been de-compacted or had gravel removed in areas that should be Interim Reclamation.

Inspection Photos: Laramie Buzzard Creek Loc#311747

September 5, 2016