

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2016

Document Number:

680101110

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 298297 | 334442 | Colby, Lou | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|------------------------------|---------------------|
| | | wbankert@laramie-energy.com | |
| Prescott, Lorne | (970) 812-5311 | lprescott@laramie-energy.com | Enviro Pice/Laramie |

Compliance Summary:QtrQtr: NESW Sec: 4 Twp: 10S Range: 93W**Inspector Comment:**

This is an Abandoned Location Inspection for Wells API#s 077-09753, 09787, 09799, 09800, 09801, 09802, 09803, 09804, 09812, 09813, 09814, 09815, 09816, 09817, 09818. It does not appear that these AL Wells were drilled on Location with Four other Producing Wells; therefore these are Well releases on an Active Location. APDs were first approved in 2008 for Delta Petroleum and Abandoned 5/19/2016 by Laramie Energy.

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|-------------------------------------|
| 289176 | WELL | PR | 01/21/2008 | GW | 077-09238 | VEGA UNIT 4-241 | PR | <input type="checkbox"/> |
| 293964 | WELL | PR | 12/14/2007 | GW | 077-09461 | VEGA 4-331 | PR | <input type="checkbox"/> |
| 293988 | WELL | PR | 12/18/2007 | GW | 077-09464 | VEGA 4-231 | PR | <input type="checkbox"/> |
| 293989 | WELL | PR | 12/18/2007 | GW | 077-09465 | VEGA 4-234 | PR | <input type="checkbox"/> |
| 298297 | WELL | AL | 05/19/2016 | LO | 077-09753 | Vega 4-223 | RI | <input checked="" type="checkbox"/> |
| 299161 | WELL | AL | 05/19/2016 | LO | 077-09787 | Vega 4-324 | RI | <input checked="" type="checkbox"/> |
| 299352 | WELL | AL | 05/19/2016 | LO | 077-09799 | Vega 4-134 | RI | <input checked="" type="checkbox"/> |
| 299353 | WELL | AL | 05/19/2016 | LO | 077-09800 | Vega 4-132 | RI | <input checked="" type="checkbox"/> |
| 299354 | WELL | AL | 05/19/2016 | LO | 077-09801 | Vega 4-224 | RI | <input checked="" type="checkbox"/> |
| 299355 | WELL | AL | 05/19/2016 | LO | 077-09802 | Vega 4-131 | RI | <input checked="" type="checkbox"/> |

Inspector Name: Colby, Lou

| | | | | | | | | |
|--------|------|----|------------|----|-----------|------------|----|---|
| 299356 | WELL | AL | 05/19/2016 | LO | 077-09803 | Vega 4-222 | RI | X |
| 299357 | WELL | AL | 05/19/2016 | LO | 077-09804 | Vega 4-221 | RI | X |
| 299524 | WELL | AL | 05/19/2016 | LO | 077-09812 | Vega 4-133 | RI | X |
| 299525 | WELL | AL | 05/19/2016 | LO | 077-09813 | Vega 4-141 | RI | X |
| 299526 | WELL | AL | 05/19/2016 | LO | 077-09814 | Vega 4-143 | RI | X |
| 299527 | WELL | AL | 05/19/2016 | LO | 077-09815 | Vega 4-232 | RI | X |
| 299528 | WELL | AL | 05/19/2016 | LO | 077-09816 | Vega 4-233 | RI | X |
| 299529 | WELL | AL | 05/19/2016 | LO | 077-09817 | Vega 4-142 | RI | X |
| 299530 | WELL | AL | 05/19/2016 | LO | 077-09818 | Vega 4-144 | RI | X |

Equipment:

Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Emergency Contact Number (S/AR): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

Venting:

| | |
|---------|--|
| Yes/No | |
| Comment | |

Flaring:

| | | | |
|--------------------|--|------------------------------|--|
| Type | | Satisfactory/Action Required | |
| Comment: | | | |
| Corrective Action: | | Correct Action Date: | |

Predrill

Location ID: 298297

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 298297 Type: WELL API Number: 077-09753 Status: AL Insp. Status: RI

Facility ID: 299161 Type: WELL API Number: 077-09787 Status: AL Insp. Status: RI

Facility ID: 299352 Type: WELL API Number: 077-09799 Status: AL Insp. Status: RI

Facility ID: 299353 Type: WELL API Number: 077-09800 Status: AL Insp. Status: RI

Facility ID: 299354 Type: WELL API Number: 077-09801 Status: AL Insp. Status: RI

Facility ID: 299355 Type: WELL API Number: 077-09802 Status: AL Insp. Status: RI

Facility ID: 299356 Type: WELL API Number: 077-09803 Status: AL Insp. Status: RI

Inspector Name: Colby, Lou

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 299357 | Type: WELL | API Number: 077-09804 | Status: AL | Insp. Status: RI |
| Facility ID: 299524 | Type: WELL | API Number: 077-09812 | Status: AL | Insp. Status: RI |
| Facility ID: 299525 | Type: WELL | API Number: 077-09813 | Status: AL | Insp. Status: RI |
| Facility ID: 299526 | Type: WELL | API Number: 077-09814 | Status: AL | Insp. Status: RI |
| Facility ID: 299527 | Type: WELL | API Number: 077-09815 | Status: AL | Insp. Status: RI |
| Facility ID: 299528 | Type: WELL | API Number: 077-09816 | Status: AL | Insp. Status: RI |
| Facility ID: 299529 | Type: WELL | API Number: 077-09817 | Status: AL | Insp. Status: RI |
| Facility ID: 299530 | Type: WELL | API Number: 077-09818 | Status: AL | Insp. Status: RI |

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Inspector Name: Colby, Lou

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____

Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: There is no evidence of the AL Wells on this Active Location.

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Pass _____

Well Release on Active Location ☒

Multi-Well Location ☒

Inspector Name: Colby, Lou

| | | | | | | |
|---------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Storm Water: | | | | | | |
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| | | | | | | |

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 680101111 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3953939 |