

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
09/05/2016
Document Number:
680101110
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
	<u>298297</u>	<u>334442</u>	<u>Colby, Lou</u>		

Operator Information:

OGCC Operator Number: <u>10433</u>
Name of Operator: <u>LARAMIE ENERGY LLC</u>
Address: <u>1401 SEVENTEENTH STREET #1400</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		wbankert@laramie-energy.com	
Prescott, Lorne	(970) 812-5311	lprescott@laramie-energy.com	Enviro Pice/Laramie

Compliance Summary:

QtrQtr: NESW Sec: 4 Twp: 10S Range: 93W

Inspector Comment:

This is an Abandoned Location Inspection for Wells API#s 077-09753, 09787, 09799, 09800, 09801, 09802, 09803, 09804, 09812, 09813, 09814, 09815, 09816, 09817, 09818. It does not appear that these AL Wells were drilled on Location with Four other Producing Wells; therefore these are Well releases on an Active Location. APDs were first approved in 2008 for Delta Petroleum and Abandoned 5/19/2016 by Laramie Energy.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
289176	WELL	PR	01/21/2008	GW	077-09238	VEGA UNIT 4-241	PR	<input type="checkbox"/>
293964	WELL	PR	12/14/2007	GW	077-09461	VEGA 4-331	PR	<input type="checkbox"/>
293988	WELL	PR	12/18/2007	GW	077-09464	VEGA 4-231	PR	<input type="checkbox"/>
293989	WELL	PR	12/18/2007	GW	077-09465	VEGA 4-234	PR	<input type="checkbox"/>
298297	WELL	AL	05/19/2016	LO	077-09753	Vega 4-223	RI	<input checked="" type="checkbox"/>
299161	WELL	AL	05/19/2016	LO	077-09787	Vega 4-324	RI	<input checked="" type="checkbox"/>
299352	WELL	AL	05/19/2016	LO	077-09799	Vega 4-134	RI	<input checked="" type="checkbox"/>
299353	WELL	AL	05/19/2016	LO	077-09800	Vega 4-132	RI	<input checked="" type="checkbox"/>
299354	WELL	AL	05/19/2016	LO	077-09801	Vega 4-224	RI	<input checked="" type="checkbox"/>
299355	WELL	AL	05/19/2016	LO	077-09802	Vega 4-131	RI	<input checked="" type="checkbox"/>

Inspector Name: Colby, Lou

299356	WELL	AL	05/19/2016	LO	077-09803	Vega 4-222	RI	<input checked="" type="checkbox"/>
299357	WELL	AL	05/19/2016	LO	077-09804	Vega 4-221	RI	<input checked="" type="checkbox"/>
299524	WELL	AL	05/19/2016	LO	077-09812	Vega 4-133	RI	<input checked="" type="checkbox"/>
299525	WELL	AL	05/19/2016	LO	077-09813	Vega 4-141	RI	<input checked="" type="checkbox"/>
299526	WELL	AL	05/19/2016	LO	077-09814	Vega 4-143	RI	<input checked="" type="checkbox"/>
299527	WELL	AL	05/19/2016	LO	077-09815	Vega 4-232	RI	<input checked="" type="checkbox"/>
299528	WELL	AL	05/19/2016	LO	077-09816	Vega 4-233	RI	<input checked="" type="checkbox"/>
299529	WELL	AL	05/19/2016	LO	077-09817	Vega 4-142	RI	<input checked="" type="checkbox"/>
299530	WELL	AL	05/19/2016	LO	077-09818	Vega 4-144	RI	<input checked="" type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/AR): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No	_____
Comment	_____

Flaring:

Type	_____	Satisfactory/Action Required	_____
Comment:	_____		
Corrective Action:	_____	Correct Action Date:	_____

Predrill

Location ID: 298297
 Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
S/AR: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____
CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____
CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: <u>298297</u>	Type: <u>WELL</u>	API Number: <u>077-09753</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>299161</u>	Type: <u>WELL</u>	API Number: <u>077-09787</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>299352</u>	Type: <u>WELL</u>	API Number: <u>077-09799</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>299353</u>	Type: <u>WELL</u>	API Number: <u>077-09800</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>299354</u>	Type: <u>WELL</u>	API Number: <u>077-09801</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>299355</u>	Type: <u>WELL</u>	API Number: <u>077-09802</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>299356</u>	Type: <u>WELL</u>	API Number: <u>077-09803</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>

Facility ID: <u>299357</u>	Type: <u>WELL</u>	API Number: <u>077-09804</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>299524</u>	Type: <u>WELL</u>	API Number: <u>077-09812</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>299525</u>	Type: <u>WELL</u>	API Number: <u>077-09813</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>299526</u>	Type: <u>WELL</u>	API Number: <u>077-09814</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>299527</u>	Type: <u>WELL</u>	API Number: <u>077-09815</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>299528</u>	Type: <u>WELL</u>	API Number: <u>077-09816</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>299529</u>	Type: <u>WELL</u>	API Number: <u>077-09817</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>299530</u>	Type: <u>WELL</u>	API Number: <u>077-09818</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment:
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment:
 1003a. Waste and Debris removed? _____
 CM _____
 CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: There is no evidence of the AL Wells on this Active Location.

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Pass _____ Well Release on Active Location Multi-Well Location

Inspector Name: Colby, Lou

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680101110	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3953941
680101111	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3953939