



Photo#1: Overview of Location from Entry to SE

September 5, 2016

Inspection Photos: Laramie Vega Loc#334442



Photo#2: View to North; Location Footprint has not been Reduced

September 5, 2016

Inspection Photos: Laramie Vega Loc#334442



Photo#3: View NE; Large areas of Location have not been Reclaimed for Interim Reclamation.

September 5, 2016

Inspection Photos: Laramie Vega Loc#334442