

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2016

Document Number:

680101109

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	334442	334442	Colby, Lou	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Prescott, Lorne	(970) 812-5311	lprescott@laramie-energy.com	Enviro Pice/Laramie
		wbankert@laramie-energy.com	

Compliance Summary:QtrQtr: NESW Sec: 4 Twp: 10S Range: 93W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/02/2015	675202011			ACTION REQUIRED			No
11/21/2014	675200792			ACTION REQUIRED			No
06/04/2014	675200030			ACTION REQUIRED			No

Inspector Comment:

This is an Interim Reclamation and Stormwater focused Inspection. Any Corrective Actions from previous Inspections that have not been addressed are still applicable. This is a Follow Up to Insp.Doc#675202011 Dated 9/2/2015.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
289176	WELL	PR	01/21/2008	GW	077-09238	VEGA UNIT 4-241	RI	<input checked="" type="checkbox"/>
293964	WELL	PR	12/14/2007	GW	077-09461	VEGA 4-331	RI	<input checked="" type="checkbox"/>
293988	WELL	PR	12/18/2007	GW	077-09464	VEGA 4-231	RI	<input checked="" type="checkbox"/>
293989	WELL	PR	12/18/2007	GW	077-09465	VEGA 4-234	RI	<input checked="" type="checkbox"/>
298297	WELL	AL	05/19/2016	LO	077-09753	Vega 4-223	RI	<input checked="" type="checkbox"/>
299161	WELL	AL	05/19/2016	LO	077-09787	Vega 4-324	RI	<input checked="" type="checkbox"/>
299352	WELL	AL	05/19/2016	LO	077-09799	Vega 4-134	RI	<input checked="" type="checkbox"/>

Inspector Name: Colby, Lou

299353	WELL	AL	05/19/2016	LO	077-09800	Vega 4-132	RI	<input checked="" type="checkbox"/>
299354	WELL	AL	05/19/2016	LO	077-09801	Vega 4-224	RI	<input checked="" type="checkbox"/>
299355	WELL	AL	05/19/2016	LO	077-09802	Vega 4-131	RI	<input checked="" type="checkbox"/>
299356	WELL	AL	05/19/2016	LO	077-09803	Vega 4-222	RI	<input checked="" type="checkbox"/>
299357	WELL	AL	05/19/2016	LO	077-09804	Vega 4-221	RI	<input checked="" type="checkbox"/>
299524	WELL	AL	05/19/2016	LO	077-09812	Vega 4-133	RI	<input checked="" type="checkbox"/>
299525	WELL	AL	05/19/2016	LO	077-09813	Vega 4-141	RI	<input checked="" type="checkbox"/>
299526	WELL	AL	05/19/2016	LO	077-09814	Vega 4-143	RI	<input checked="" type="checkbox"/>
299527	WELL	AL	05/19/2016	LO	077-09815	Vega 4-232	RI	<input checked="" type="checkbox"/>
299528	WELL	AL	05/19/2016	LO	077-09816	Vega 4-233	RI	<input checked="" type="checkbox"/>
299529	WELL	AL	05/19/2016	LO	077-09817	Vega 4-142	RI	<input checked="" type="checkbox"/>
299530	WELL	AL	05/19/2016	LO	077-09818	Vega 4-144	RI	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/AR): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Venting:**

Yes/No _____

Comment _____

Flaring:

Type _____ Satisfactory/Action Required _____

Comment: _____

Inspector Name: Colby, Lou

Corrective Action:

Correct Action
Date:

Predrill

Location ID: 334442

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____

CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 289176 Type: WELL API Number: 077-09238 Status: PR Insp. Status: RI

Facility ID: 293964 Type: WELL API Number: 077-09461 Status: PR Insp. Status: RI

Facility ID: 293988 Type: WELL API Number: 077-09464 Status: PR Insp. Status: RI

Facility ID: 293989 Type: WELL API Number: 077-09465 Status: PR Insp. Status: RI

Facility ID: 298297 Type: WELL API Number: 077-09753 Status: AL Insp. Status: RI

Facility ID: 299161 Type: WELL API Number: 077-09787 Status: AL Insp. Status: RI

Inspector Name: Colby, Lou

Facility ID: 299352	Type: WELL	API Number: 077-09799	Status: AL	Insp. Status: RI
Facility ID: 299353	Type: WELL	API Number: 077-09800	Status: AL	Insp. Status: RI
Facility ID: 299354	Type: WELL	API Number: 077-09801	Status: AL	Insp. Status: RI
Facility ID: 299355	Type: WELL	API Number: 077-09802	Status: AL	Insp. Status: RI
Facility ID: 299356	Type: WELL	API Number: 077-09803	Status: AL	Insp. Status: RI
Facility ID: 299357	Type: WELL	API Number: 077-09804	Status: AL	Insp. Status: RI
Facility ID: 299524	Type: WELL	API Number: 077-09812	Status: AL	Insp. Status: RI
Facility ID: 299525	Type: WELL	API Number: 077-09813	Status: AL	Insp. Status: RI
Facility ID: 299526	Type: WELL	API Number: 077-09814	Status: AL	Insp. Status: RI
Facility ID: 299527	Type: WELL	API Number: 077-09815	Status: AL	Insp. Status: RI
Facility ID: 299528	Type: WELL	API Number: 077-09816	Status: AL	Insp. Status: RI
Facility ID: 299529	Type: WELL	API Number: 077-09817	Status: AL	Insp. Status: RI
Facility ID: 299530	Type: WELL	API Number: 077-09818	Status: AL	Insp. Status: RI

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment:
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: **Interim Reclamation has not been installed**1003a. Waste and Debris removed? Pass

CM _____

CA _____

CA Date _____

Unused or unneeded equipment onsite? Pass

CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? Pass

CM _____

CA _____

CA Date _____

Guy line anchors marked? _____

CM _____

CA _____

CA Date _____

1003b. Area no longer in use? FailProduction areas stabilized ? Pass1003c. Compacted areas have been cross ripped? Fail1003d. Drilling pit closed? PassSubsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? FailProduction areas have been stabilized? PassSegregated soils have been replaced? Fail**RESTORATION AND REVEGETATION**Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-CroplandTop soil replaced FailRecontoured Fail80% Revegetation Fail1003 f. Weeds Noxious weeds? PComment: **Location Footprint has not been reduced since Completion of 4 PR Wells on Location. Interim Reclamation should be installed in Areas no longer needed for Use or Production. CA Date; Reclamation Activities to be complete by end of Spring 2017.**Overall Interim Reclamation Fail**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Inspector Name: Colby, Lou

Access Roads Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____
Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
Compaction alleviation _____ Dust and erosion control _____
Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
Weeds present _____ Subsidence _____

Comment:

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Berms	Pass					
Gravel	Pass					

S/A/V: SATISFACTORY

Corrective Date: _____

Comment:

CA:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680101119	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3953949