

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2016

Document Number:

680101117

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	295230	334439	Colby, Lou	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Prescott, Lorne	(970) 812-5311	lprescott@laramie-energy.com	Enviro Pice/Laramie
		wbankert@laramie-energy.com	

Compliance Summary:QtrQtr: NESE Sec: 4 Twp: 10S Range: 93W**Inspector Comment:**

This is an Abandoned Location Inspection for Wells API#s 077-09567, 09568, 09569, 09570, 09571, 09572, 09789, 09790, 09791, 09792, 09793, 09794, 09795, 09805, 09806, 10083, APDs first approved in 2008, Abandoned 5/18/2016.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
295230	WELL	AL	05/18/2016	LO	077-09567	Vega Unit 3-141	RI	<input checked="" type="checkbox"/>
295231	WELL	AL	05/18/2016	LO	077-09568	Vega Unit 4-444	RI	<input checked="" type="checkbox"/>
295232	WELL	AL	05/18/2016	LO	077-09569	Vega 4-334	RI	<input checked="" type="checkbox"/>
295233	WELL	AL	05/18/2016	LO	077-09570	Vega 4-431	RI	<input checked="" type="checkbox"/>
295234	WELL	AL	05/18/2016	LO	077-09571	Vega 4-434	RI	<input checked="" type="checkbox"/>
295235	WELL	AL	05/18/2016	LO	077-09572	Vega Unit 4-441	RI	<input checked="" type="checkbox"/>
299245	WELL	AL	05/18/2016	LO	077-09789	Vega 4-433	RI	<input checked="" type="checkbox"/>
299246	WELL	AL	05/18/2016	LO	077-09790	Vega Unit 4-443	RI	<input checked="" type="checkbox"/>
299247	WELL	AL	05/18/2016	LO	077-09791	Vega 4-333	RI	<input checked="" type="checkbox"/>
299248	WELL	AL	05/18/2016	LO	077-09792	Vega Unit 4-342	RI	<input checked="" type="checkbox"/>

Inspector Name: Colby, Lou

299249	WELL	AL	05/18/2016	LO	077-09793	Vega 04-09B	RI	<input checked="" type="checkbox"/>
299251	WELL	AL	05/18/2016	LO	077-09794	Vega 4-332	RI	<input checked="" type="checkbox"/>
299252	WELL	AL	05/18/2016	LO	077-09795	Vega Unit 4-442	AL	<input checked="" type="checkbox"/>
299358	WELL	AL	05/18/2016	LO	077-09805	Vega 04-07B	RI	<input checked="" type="checkbox"/>
299359	WELL	AL	05/18/2016	LO	077-09806	Vega 4-423	AL	<input checked="" type="checkbox"/>
416277	WELL	AL	05/18/2016	LO	077-10083	VEGA FED 03-11D	RI	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/AR): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	_____
Comment	_____

Flaring:

Type	_____	Satisfactory/Action Required	_____
Comment:	_____		
Corrective Action:	_____	Correct Action Date:	_____

Predrill

Location ID: 295230

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 295230 Type: WELL API Number: 077-09567 Status: AL Insp. Status: RI

Facility ID: 295231 Type: WELL API Number: 077-09568 Status: AL Insp. Status: RI

Facility ID: 295232 Type: WELL API Number: 077-09569 Status: AL Insp. Status: RI

Facility ID: 295233 Type: WELL API Number: 077-09570 Status: AL Insp. Status: RI

Facility ID: 295234 Type: WELL API Number: 077-09571 Status: AL Insp. Status: RI

Facility ID: 295235 Type: WELL API Number: 077-09572 Status: AL Insp. Status: RI

Facility ID: 299245 Type: WELL API Number: 077-09789 Status: AL Insp. Status: RI

Facility ID: 299246	Type: WELL	API Number: 077-09790	Status: AL	Insp. Status: RI
Facility ID: 299247	Type: WELL	API Number: 077-09791	Status: AL	Insp. Status: RI
Facility ID: 299248	Type: WELL	API Number: 077-09792	Status: AL	Insp. Status: RI
Facility ID: 299249	Type: WELL	API Number: 077-09793	Status: AL	Insp. Status: RI
Facility ID: 299251	Type: WELL	API Number: 077-09794	Status: AL	Insp. Status: RI
Facility ID: 299252	Type: WELL	API Number: 077-09795	Status: AL	Insp. Status: AL
Facility ID: 299358	Type: WELL	API Number: 077-09805	Status: AL	Insp. Status: RI
Facility ID: 299359	Type: WELL	API Number: 077-09806	Status: AL	Insp. Status: AL
Facility ID: 416277	Type: WELL	API Number: 077-10083	Status: AL	Insp. Status: RI

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

Inspector Name: Colby, Lou

CM _____

CA _____

CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____

CA Date _____

Guy line anchors marked? _____

CM _____

CA _____

CA Date _____

1003b. Area no longer in use? _____

Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____

Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads

Regraded

Fail

Contoured

Fail

Culverts removed

Fail

Gravel removed

Fail

Location and associated production facilities reclaimed

Fail

Locations, facilities, roads, recontoured

Fail

Compaction alleviation

Fail

Dust and erosion control

Fail

Non cropland: Revegetated 80%

Fail

Cropland: perennial forage _____

Weeds present In Process

Subsidence

Pass

Comment: _____

APDs have not been drilled, Permits were Abandoned 5/18/2016. No Wells were observed. Location was constructed and needs Final Reclamation. 2A for this Location could not be found in COGCC Files. Small Populations of Noxious weeds were noted on Loc

Inspector Name: Colby, Lou

Corrective Action:	Reclaim Location. Perform Final Reclamation per COGCC 1004 Rules. Reclamation Activities to be complete by June 15, 20162017. Refer to Photos attached for detail of Site Conditions.	Date	06/15/2017
--------------------	---	------	------------

Overall Final Reclamation **Fail** Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps	Pass					
Drains	Pass	Sodding	Fail			
Ditches	Pass					

S/A/V: **ACTION REQUIRED** Corrective Date: **06/15/2017**

Comment: **Erosion noted on Fill Slope where it borders Access Road leading to adjacent Location.**

CA: **Incorporate SW controls and appropriate BMPs upon Reclamation of Location.**

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680101117	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3956661
680101133	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3956659