



Photo#1: Entry Sign



Photo#2: View of Location from County Rd to SE

September 20, 2016

Inspection Photos: Porter B



Photo#3: Well has been P&A'd

September 20, 2016

Inspection Photos: Porter B



Photo#4: Overview of Location from top of Cut Slope to West

September 20, 2016

Inspection Photos: Porter B



Photo#5: Overview of Location to South

September 20, 2016

Inspection Photos: Porter B



Photo#6: View of Cut Slope to East.

September 20, 2016

Inspection Photos: Porter B



Photo#&7: Erosion on Cut Slope.

September 20, 2016

Inspection Photos: Porter B



Photo#8: Access Road to Location.

September 20, 2016

Inspection Photos: Porter B