

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/27/2016

Submitted Date:

09/27/2016

Document Number:

673403682**FIELD INSPECTION FORM**

Loc ID 313049 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 51922Name of Operator: LYSTER OIL COMPANY INCAddress: 701 COUNTY ROAD 105City: CRAIG State: CO Zip: 81625**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Lyster, Larry	970-824-6854	lysteroil@yahoo.com	
lyster, brandon	970-326-7533	blysteroil@aol.com	owner operator

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223465	WELL	PR	07/05/1995	OW	081-06831	ELK SPRINGS 24-8	PR

**General Comment:**

<b>Inspected Facilities</b>				
Facility ID: 223465	Type: WELL	API Number: 081-06831	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Pumping.			
Corrective Action:				Date:

**Optical Gas Imaging Survey**Survey Type: LDARCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 40.324490 Long: -108.420080Wind: None Speed:          (mph) Direction From:          Weather: Clear Temperature: 61 (F)Assisting Staff Emily Waldron Camera #:         ☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
11:40	AM	11:45	AM

Equipment
Wellhead(s)
Oil Tank(s)

Comment: Corrective Action: 

Date:

**COGCC Comments**

Comment	User	Date
<a href="#">Follow up to inspection from 8/25/2016 document number 673403554. All corrective actions have been met.</a>	waldrone	09/27/2016