

On September 2, 2016 COGCC Environmental Field Inspection of ARCH OIL AND GAS (Arch) J.P Weise  
#2 Location ID: 312774.



Location sign.



Pump Jack.



Well head.



Waddle in disrepair.



Waddle in disrepair.



Land treatment area.



Landtreatment, tank battery, and pump jack.



Land treatment area.



Land treatment area. Note: animal tracks.



Compromised liner.



Oil staining on soil.



Oil staining on soil.



Tank battery bermed with weeds.



Oil staining from weld.



Tank loadout.