



photo 1: Well sign.



photo 2: Facing northeast toward the location.



photo 3: Facing southwest toward the location.



photo 4: Facing toward the north slope of the location. There were noxious weeds (Canada thistle) growing in this area.



photo 5: Noxious weeds (Canada thistle) were found along the north slope of the location.



photo 6: North side of the location facing southeast.