

# Grynberg Petroleum Company

## September 2016 Report

Chivington #1

API 05-081-05709

SESE section 20 12N 97W

Project #8333 Wellsite Reclamation

Received results from resample on September 23, requested revisions

Received revised report on September 26

Analyzed and disseminated report results

Sample location 4B is above allowable table 910-1 values for TPH

Remediation of the balance of the pits will start when soil samples have passed COGCC requirements.

Continue monitoring of surface water and potential runoff/runon across disturbance.