

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/03/2016

Submitted Date:

10/03/2016

Document Number:

666802630**FIELD INSPECTION FORM**

Loc ID 335157 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	<a href="#">Sr. EH&amp;S</a>
Axelsson, Aaron	970-230-0926	aaxelson@vnrlc.com	<a href="#">Sr. Production Foreman</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292114	WELL	PR	05/20/2008	GW	045-14600	SPECIALTY 34A-21-692	PR
292945	WELL	PR	05/27/2008	GW	045-14819	SPECIALTY 34C-21-692	PR
292946	WELL	PR	05/23/2008	GW	045-14820	SPECIALTY 33C-21-692	PR
292947	WELL	PR	05/30/2008	GW	045-14821	SPECIALTY 44C-21-692	PR
292948	WELL	PR	08/11/2008	GW	045-14822	SPECIALTY 43A-21-692	PR
292949	WELL	PR	08/10/2008	GW	045-14823	SPECIALTY 43C-21-692	PR
292950	WELL	PR	07/31/2008	GW	045-14824	SPECIALTY 44A-21-692	PR
292951	WELL	PR	05/25/2008	GW	045-14825	SPECIALTY 33A-21-692	PR

**General Comment:**[Shared facilities with location ID 335497](#)

**Location**Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-1657-001		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Equipment:**

Type: Emission Control Device	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 16		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	10	500 BBLS	STEEL AST		39.508505,-107.668751
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)		

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	292114	Type:	WELL	API Number:	045-14600	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	292945	Type:	WELL	API Number:	045-14819	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	292946	Type:	WELL	API Number:	045-14820	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	292947	Type:	WELL	API Number:	045-14821	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	292948	Type:	WELL	API Number:	045-14822	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	292949	Type:	WELL	API Number:	045-14823	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	292950	Type:	WELL	API Number:	045-14824	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	292951	Type:	WELL	API Number:	045-14825	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			

--

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Slope Roughening						
Berms						
		Gravel	Pass			
		Check Dams	Pass			
		Culverts	Pass			
		Ditches	Pass			
Ditches						
		Sediment Traps	Pass			
Seeding						

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT