

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/27/2016

Submitted Date:

10/03/2016

Document Number:

685100069**FIELD INSPECTION FORM**Loc ID 311810 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
haub, Michael	970-697-8385	mhaub@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229226	WELL	IJ	05/06/1995	DSPW	103-06316	MCLAUGHLIN, A C 44	EI
447693	SPILL OR RELEASE	AC	09/19/2016		-	SPILL/RELEASE POINT	EI

General Comment:

On 9/27/2016 COGCC Environmental staff inspected spill location 447693, spill number 401102355. Weather was sunny and 69 degrees; there was evidence field wide that the area had experienced rains recently. Using the information provided on spill reports, the inspector attempted to determine that location in the field. Not enough information was provided in the spill reports to determine the location of spill/discharge release point. Please provide updated lat/long for the spill point to Kris Neidel. Well 103-06316, AC Mclaughlin 44 wellpad was inspected, no production equipment on location. Location berm around location.

Inspected Facilities									
Facility ID:	229226	Type:	WELL	API Number:	103-06316	Status:	IJ	Insp. Status:	EI
Facility ID:	447693	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI