

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/05/2016

Submitted Date:

10/05/2016

Document Number:

681901507

**FIELD INSPECTION FORM**

Loc ID 305194 Inspector Name: HELGELAND, GARY On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		COGCCinspections@anadarko.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275370	WELL	PR	05/10/2005	GW	123-22626	FT. LUPTON HIGHLANDS 41-9	PR

**General Comment:**

**Inspected Facilities**

Facility ID: 275370 Type: WELL API Number: 123-22626 Status: PR Insp. Status: PR

**Cement**

Cement Contractor

Contractor Name: Schlumberger

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): \_\_\_\_\_

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Cement Type: \_\_\_\_\_

Comment: BASIC RIG #1662 ON LOCATION. PUMPED NIOBRARA BALANCE PLUG: PUMPED 40 SXS 15.8 PPG CEMENT. PUH TO 4880' RU CEMENTERS. PUMPED SUSSEX BALANCE PLUG: 40 SXS 15.8 PPG CEMENT. WOC

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_