

# Final Reclamation Inspection- Overview



Photo taken using COGCC GISOnline database illustrating historic PA location in relation to an active Crestone Peak location (Location ID 416456). Historic PA location API #123-10057 is within the boundaries of an active location; therefore, this is a well release on an active location.

# Final Reclamation Inspection



**Photo 1.** Photo taken from approximate well location, facing North. Historic PA location is within the boundaries of an active location.

# Final Reclamation Inspection



**Photo 2.** Photo taken of a sign operated by Crestone Peak confirming active location.