



**photo 1:** Facing west along the reclaimed access road toward the location.



**photo 2:** Facing west toward the location.



**photo 3:** Northeast side of the location facing southwest.



**photo 4:** The sterile annual cover crop (Triticale) is the dominant vegetation at the location.



**photo 5:** Northwest side of the location facing southeast.



**photo 6:** Southwest side of the location facing northeast.



**photo 7:** There is perennial vegetation establishing at the location which appears to be establishing better where the cover crop (Triticale) is less dominant.



**photo 8:** There is BMP's installed at a swale at the north side of the location.