

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/17/2016

Submitted Date:

10/17/2016

Document Number:

674703236**FIELD INSPECTION FORM**
 Loc ID 335211 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 53650Name of Operator: MARATHON OIL COMPANYAddress: 1501 STAMPEDE AVENUECity: CODY State: WY Zip: 82414**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Stebbins, Tiffany	307-527-2223	tastebbins@marathonoil.com	<a href="#">Regulatory Compli Rep (Wyoming)</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291568	WELL	PR	09/01/2011	GW	045-14441	CHEVRON-MARATHON 41A-22D	PR
291570	WELL	PR	09/01/2011	GW	045-14440	CHEVRON-MARATHON 14D-14D	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 866-662-2378

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS	
PRODUCED WATER	1	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tanak ID	SE GPS	
CONDENSATE	1	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:		Date:				

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:	Date:		

**Flaring:**

Type			
Comment:			
Corrective Action:	Date:		

**Inspected Facilities**Facility ID: 291568 Type: WELL API Number: 045-14441 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 291570 Type: WELL API Number: 045-14440 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Ditches	Pass			
Ditches	Pass					
Gravel	Pass					
Seeding	Pass					
		Compaction	Pass			
		Culverts	Pass			
		Gravel	Pass			
Berms	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT