

# Reclamation Inspection

10/18/2016

Operator: Rex Monahan

Location ID: 387453

Logan County, CO

SWNW Section 25 T7N R53W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**

Department of Natural Resources



**Figure 1:** Photo of GPS confirming location.





**Figure 2:** Photo taken from the location, facing north. Photo shows concrete pump base has not been removed.

**Figure 3:** Photo taken from the location, facing east. Photo shows concrete block has been removed.



**Figure 4:** Photo taken from the location, facing south. Photo shows concrete block has been removed.



**Figure 5:** Photo taken from the location, facing west. Photo shows concrete block has been removed.

**Figure 6:** Photo taken from the pit location, northwest of well, facing southeast. Photo show's pit has been closed, and area where pit existed is currently used by the surface owner for storing equipment.

**Figure 7:** Photo taken from the pit location, northwest of well, facing south. Photo show's pit has been closed, and area where pit existed is currently used by the surface owner for storing equipment



**Figure 8:** Photo taken from the pit location, northwest of well, facing southwest. Photo show's pit has been closed, and area where pit existed is currently used by the surface owner for storing equipment.