

## Cover Data

Date:

**Inspected By:**

Location/Operator:

API# 071-09029

[illegible]

2nd= second hit; P= plant species present but not hit





**photo 1:** Beginning of transect facing southeast at the location (disturbed).



**photo 2:** End of transect facing northwest at the location (disturbed).





**photo 3:** Beginning of transect facing west at the reference area.



**photo 4:** End of transect facing east at the reference area.