

Photo#1

Beginning of Disturbed Area Transect #1, facing East



Photo#2

Ground view at midpoint of Transect #1



Photo#3:

View North at midpoint of Transect #1 .



Photo#4:

View South at midpoint of Transect.#1




Photo#5:

End of Transect #1 facing West



Photo#6:

Beginning of Reference Area Transect #2, facing East



Photo#7:

Ground view at midpoint of Transect #2



Photo#8:

View North at midpoint of Transect #2 .



Photo#9:

View South at midpoint of Transect #2



Photo#10:

End of Transect #2 , facing West



Cover Data

Date:

Inspected By:

Location/Operator:

[illegible]

2nd = second hit, P = plant present but not hit

2nd= second hit; P= plant species present but not hit