


**Photo#1:**  
View North over Location.




**Photo#2:**  
View South over Location.



**Photo#3:**  
View East over Location.



**Photo#4:**  
View West over Location.



**Photo#5: View from top of Slope to SE over Canada Thistle population. Dark patches at base are also Thistle. Grasses have been grazed short providing visual contrast.**



October 19, 2016

Inspection Photos: Pine Ridge AL API#107-06234

**Photo#6: View to East Over Flat area of Location showing predominate Noxious Weed, Canada Thistle.**



October 19, 2016

Inspection Photos: Pine Ridge AL API#107-06234

**Photo#7: Ground view showing Houndstongue & Thistle Rosettes & Matured Plants.**



October 19, 2016

Inspection Photos: Pine Ridge AL API#107-06234

**Photo#8: Ground view in Weedy area, Grasses are struggling.**



October 19, 2016

Inspection Photos: Pine Ridge AL API#107-06234

**Photo#9&10: Erosion Channel developed at base of Location.**



October 19, 2016

Inspection Photos: Pine Ridge AL API#107-  
06234