

Reclamation Inspection

10/21/2016

Operator: Davis Oil Company

Location ID: 401767

Washington County, CO

NESW Section 30 T4N R51W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Figure 1: Photo of GPS verifying location.



Figure 2: Photo taken from the location, facing north. Photo shows vegetation over the reclamation area.



Figure 3: Photo taken from the location, facing east. Photo shows vegetation over the reclamation area.



Figure 4: Photo taken from the location, facing south. Photo shows vegetation over the reclamation area.



Figure 5: Photo taken from the location, facing west. Photo shows vegetation over the reclamation area.