

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/21/2016

Submitted Date:

10/24/2016

Document Number:

666802660**FIELD INSPECTION FORM**

Loc ID 334766 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276618	WELL	PR	08/01/2005	GW	045-10495	GMR 9-14 (N9W)	PR
276619	WELL	PR	07/03/2005	GW	045-10496	HMU 9-13(N9W)	PR
412220	WELL	PR	11/13/2009	GW	045-18443	HMU 16-3A (N9W)	PR
412221	WELL	PR	12/06/2009	GW	045-18444	HMU 16-4(N9W)	PR
412222	WELL	PR	11/30/2009	GW	045-18445	ENCANA GMR 16-5 (N9W)	PR
412223	WELL	PR	11/24/2009	GW	045-18447	HMU 9-13B (N9W)	PR
412224	WELL	PR	11/17/2009	GW	045-18448	HMU 16-6A (N9W)	PR
412385	WELL	PR	08/30/2010	GW	045-18446	HMU 9-13C2 (N9W)	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-0959-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type	#	Comment	Corrective Action	Date
Type: Pig Station	# 1			
Comment:				
Corrective Action:				
Type: Plunger Lift	# 8			
Comment:				
Corrective Action:				
Type: Horizontal Heated Separator	# 0			
Comment:				
Corrective Action:				
Type: Vertical Heated Separator	# 8			
Comment:				
Corrective Action:				
Type: Ancillary equipment	# 1			
Comment:		Chemical unit at wellhead		
Corrective Action:				
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:				

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
----------	---	----------	------	----------	--------

OTHER	0				
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS	
CONDENSATE	3	500 BBLs	STEEL AST		39.453444,-107.782861	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	276618	Type:	WELL	API Number:	045-10495	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	276619	Type:	WELL	API Number:	045-10496	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	412220	Type:	WELL	API Number:	045-18443	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	412221	Type:	WELL	API Number:	045-18444	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	412222	Type:	WELL	API Number:	045-18445	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	412223	Type:	WELL	API Number:	045-18447	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	412224	Type:	WELL	API Number:	045-18448	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	412385	Type:	WELL	API Number:	045-18446	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				

--

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Rip Rap	Pass					
		Ditches	Pass			
Seeding	Pass					
Gravel	Pass					
		Culverts	Pass			
		Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT