

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/19/2016

Submitted Date:

10/19/2016

Document Number:

672500036**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 442427 Gomez, Jason 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10311Name of Operator: SYNERGY RESOURCES CORPORATIONAddress: 20203 HIGHWAY 60City: PLATTEVILLE State: CO Zip: 80651**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pennington, David		dpennington@syrinfo.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442421	WELL	DG	05/13/2016	LO	123-41847	Fagerberg 36C-7-M	WO
442422	WELL	WO	07/08/2016	LO	123-41848	Fagerberg 25N-7B-M	WO
442423	WELL	DG	07/08/2016	LO	123-41849	Fagerberg 11C-7-M	WO
442424	WELL	DG	05/13/2016	LO	123-41850	Fagerberg 28N-18B-M	WO
442425	WELL	WO	07/08/2016	LO	123-41851	Fagerberg 25N(S)-7B-M	WO
442426	WELL	DG	07/08/2016	LO	123-41852	Fagerberg 23N-7C-M	WO
442428	WELL	DG	05/13/2016	LO	123-41853	Fagerberg 36N-7B-M	WO
442429	WELL	WO	07/08/2016	LO	123-41854	Fagerberg 25N-7C-M	WO
442430	WELL	DG	07/08/2016	LO	123-41855	Fagerberg 11N-7B-M	WO
445772	WELL	DG	07/04/2016		123-43180	Fagerberg 6C-7-M	WO
445773	WELL	DG	06/17/2016		123-43181	Fagerberg 15N-7A-M	WO
445774	WELL	DG	07/13/2016		123-43182	Fagerberg 6N-7C-M	WO
445775	WELL	DG	06/26/2016		123-43183	Fagerberg 11N-7A-M	WO
445776	WELL	DG	06/08/2016		123-43184	Fagerberg 3C-18-M	WO

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Emission Control Device	# 1		
Comment:	SENDING ALL GAS FROM DRILL OUT TO 1 LARGE VOLUME ECD		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	YES		
Comment:	VENTING FROM TANKS MAJORITY OF VOC SEND TO LARGE VOLUME ECD		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 442421 Type: WELL API Number: 123-41847 Status: DG Insp. Status: WO

CompletionOperation: DrilloutDate Flowback: 10/24/2016Contractor: BasicComment: Corrective Action: Date:

Facility ID: 442422 Type: WELL API Number: 123-41848 Status: WO Insp. Status: WO

CompletionOperation: DrilloutDate Flowback: Contractor: BasicComment: Corrective Action: Date:

Facility ID: 442423 Type: WELL API Number: 123-41849 Status: DG Insp. Status: WO

CompletionOperation: DrilloutDate Flowback: Contractor: BASICComment: Corrective Action: Date:

Facility ID: 442424 Type: WELL API Number: 123-41850 Status: DG Insp. Status: WO

CompletionOperation: DrilloutDate Flowback: Contractor: BASICComment: Corrective Action: Date:

Facility ID: 442425 Type: WELL API Number: 123-41851 Status: WO Insp. Status: WO

CompletionOperation: DrilloutDate Flowback: Contractor: BASICComment:

Corrective Action:		Date:	
Facility ID: 442426	Type: WELL	API Number: 123-41852	Status: DG Insp. Status: WO
Completion			
Operation: <u>Drillout</u>			
Date Flowback:			
Contractor: <u>BASIC</u>			
Comment:			
Corrective Action:			Date:
Facility ID: 442428	Type: WELL	API Number: 123-41853	Status: DG Insp. Status: WO
Completion			
Operation: <u>Drillout</u>			
Date Flowback:			
Contractor: <u>BASIC</u>			
Comment:			
Corrective Action:			Date:
Facility ID: 442429	Type: WELL	API Number: 123-41854	Status: WO Insp. Status: WO
Completion			
Operation: <u>Drillout</u>			
Date Flowback:			
Contractor: <u>BASIC</u>			
Comment:			
Corrective Action:			Date:
Facility ID: 442430	Type: WELL	API Number: 123-41855	Status: DG Insp. Status: WO
Completion			
Operation: <u>Drillout</u>			
Date Flowback:			
Contractor: <u>BASIC</u>			
Comment:			
Corrective Action:			Date:
Facility ID: 445772	Type: WELL	API Number: 123-43180	Status: DG Insp. Status: WO
Completion			
Operation: <u>Drillout</u>			
Date Flowback:			
Contractor: <u>BASIC</u>			
Comment:			

Corrective Action:		Date:							
Facility ID:	445773	Type:	WELL	API Number:	123-43181	Status:	DG	Insp. Status:	WO
Completion									
Operation: <u>Drillout</u>									
Date Flowback:									
Contractor: <u>BASIC</u>									
<u>Comment:</u>									
Corrective Action:									
Date:									
Facility ID:	445774	Type:	WELL	API Number:	123-43182	Status:	DG	Insp. Status:	WO
Completion									
Operation: <u>Swabbing</u>									
Date Flowback:									
Contractor: <u>BASIC</u>									
<u>Comment:</u>									
Corrective Action:									
Date:									
Facility ID:	445775	Type:	WELL	API Number:	123-43183	Status:	DG	Insp. Status:	WO
Completion									
Operation: <u>Drillout</u>									
Date Flowback:									
Contractor: <u>BASIC</u>									
<u>Comment:</u>									
Corrective Action:									
Date:									
Facility ID:	445776	Type:	WELL	API Number:	123-43184	Status:	DG	Insp. Status:	WO

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
672500036	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3984419