

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2016

Submitted Date:

10/26/2016

Document Number:

666802676**FIELD INSPECTION FORM**

Loc ID 324031 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211536	WELL	PR	05/28/1998	GW	045-07296	KRK 7-10B (J7E)	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run

1

Comment: Corrective Action: Date:

Type: Horizontal Heated Separator

1

Comment: Corrective Action: Date:

Type: Plunger Lift

1

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		39.460025,107.708577
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

PaintCondition Adequate Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tanak ID	SE GPS
METHANOL	2	OTHER	STEEL AST		,
Comment:	Centralized battery				

Corrective Action:		Date:	
Paint			
Condition	Adequate		
Other (Content)			
Other (Capacity) 500gal			
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Comment:			
Corrective Action:		Date:	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 211536	Type: WELL	API Number: 045-07296	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Retention Ponds	Pass					
		Gravel	Pass			
Seeding	Pass					
Gravel	Pass					
		Culverts	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT