

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2016

Submitted Date:

10/27/2016

Document Number:

675203517**FIELD INSPECTION FORM**

Loc ID 414939	Inspector Name: CONKLIN, CURTIS	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				Findings: 1 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Terra, Energy		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414961	WELL	PR	12/01/2010	GW	045-18943	GOLDSBOROUGH PA 542-10	PR
414972	WELL	PR	10/19/2011	GW	045-18944	GOLDSBOROUGH PA 421-11	PR
414973	WELL	PR	12/01/2010	GW	045-18945	GOLDSBOROUGH PA 422-11	PR
414975	WELL	PR	12/01/2010	GW	045-18946	GOLDSBOROUGH PA 12-11	PR
430993	WELL	PR	08/08/2013	GW	045-21817	Goldsborough PA 511-11	PR
430994	WELL	PR	09/11/2013	GW	045-21818	Goldsborough PA 22-11	PR
430995	WELL	PR	09/11/2013	GW	045-21819	Goldsborough PA 521-11	PR
430996	WELL	PR	08/18/2013	GW	045-21820	Goldsborough PA 321-11	PR
430997	WELL	PR	07/05/2013	GW	045-21821	Goldsborough PA 311-11	PR
430998	WELL	PR	07/05/2013	GW	045-21822	Goldsborough PA 11-11	PR
430999	WELL	PR	07/05/2013	GW	045-21823	Goldsborough PA 312-11	PR
431000	WELL	PR	09/11/2013	GW	045-21824	Goldsborough PA 522-11	PR
431001	WELL	PR	09/11/2013	GW	045-21825	Goldsborough PA 21-11	PR
431002	WELL	PR	08/13/2013	GW	045-21826	Goldsborough PA 322-11	PR
431003	WELL	PR	08/08/2013	GW	045-21827	Goldsborough PA 412-11	PR
431004	WELL	PR	08/08/2013	GW	045-21828	Goldsborough PA 411-11	PR
431005	WELL	PR	08/12/2013	GW	045-21829	Goldsborough PA 512-11	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS	
PRODUCED WATER	3	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID: <u>414961</u>	Type: <u>WELL</u>	API Number: <u>045-18943</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>414972</u>	Type: <u>WELL</u>	API Number: <u>045-18944</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>414973</u>	Type: <u>WELL</u>	API Number: <u>045-18945</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>414975</u>	Type: <u>WELL</u>	API Number: <u>045-18946</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>430993</u>	Type: <u>WELL</u>	API Number: <u>045-21817</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>430994</u>	Type: <u>WELL</u>	API Number: <u>045-21818</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>430995</u>	Type: <u>WELL</u>	API Number: <u>045-21819</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>430996</u>	Type: <u>WELL</u>	API Number: <u>045-21820</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>430997</u>	Type: <u>WELL</u>	API Number: <u>045-21821</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>430998</u>	Type: <u>WELL</u>	API Number: <u>045-21822</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>430999</u>	Type: <u>WELL</u>	API Number: <u>045-21823</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>431000</u>	Type: <u>WELL</u>	API Number: <u>045-21824</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>431001</u>	Type: <u>WELL</u>	API Number: <u>045-21825</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>431002</u>	Type: <u>WELL</u>	API Number: <u>045-21826</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>431003</u>	Type: <u>WELL</u>	API Number: <u>045-21827</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>431004</u>	Type: <u>WELL</u>	API Number: <u>045-21828</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>431005</u>	Type: <u>WELL</u>	API Number: <u>045-21829</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Gravel	Pass					
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT