

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2016

Submitted Date:

10/27/2016

Document Number:

666802679**FIELD INSPECTION FORM**

Loc ID 423182	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
------------------	------------------------------------	---	-------------------

**Operator Information:**

OGCC Operator Number: 100185

Name of Operator: ENCANA OIL & GAS (USA) INC

Address: 370 17TH ST STE 1700

City: DENVER State: CO Zip: 80202-

**Status Summary:**

☐ THIS IS A FOLLOW UP INSPECTION

☐ FOLLOW UP INSPECTION REQUIRED

☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

20 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423618	WELL	PR	09/17/2012	GW	045-20779	BENZEL 35-2HM (F25NWB)	PR
424130	WELL	PR	01/01/2014	GW	045-20841	Benzel Fee 25-8E (F25NWB)	PR
424139	WELL	PR	10/12/2012	GW	045-20842	Benzel Fee 25-7E (F25NWB)	PR
424191	WELL	PR	01/01/2014	GW	045-20843	Benzel Fee 25-1A (F25NWB)	PR
424193	WELL	PR	01/01/2014	GW	045-20844	Benzel Fee 25-1C (F25NWB)	PR
424196	WELL	PR	01/01/2014	GW	045-20845	Benzel Fee 25-8D (F25NWB)	PR
424201	WELL	PR	05/17/2012	GW	045-20846	Benzel Fee 25-8F (F25NWB)	PR
424204	WELL	PR	03/13/2012	GW	045-20847	Benzel Fee 25-1B (F25NWB)	PR
424206	WELL	PR	01/01/2014	GW	045-20848	Benzel Fee 24-16D (F25NWB)	PR
424207	WELL	PR	01/01/2014	GW	045-20849	Benzel Fee 25-7D (F25NWB)	PR
424256	WELL	PR	04/08/2013	GW	045-20871	BENZEL FEDERAL 24-15B (F25NWB)	PR
424260	WELL	PR	04/08/2013	GW	045-20873	Benzel Fee 25-3D (F25NWB)	PR
424262	WELL	PR	04/08/2013	GW	045-20874	BENZEL FEDERAL 24-14D (F25NWB)	PR
424264	WELL	PR	04/08/2013	GW	045-20876	Benzel Federal 24-10E (F25NWB)	PR
424265	WELL	PR	03/13/2013	GW	045-20877	BENZEL FEDERAL 24-14DD (F25NWB)	PR
424266	WELL	PR	04/08/2013	GW	045-20878	BENZEL FEE 25-3A (F25NWB)	PR

424267	WELL	PR	04/08/2013	GW	045-20879	Benzel Federal 24-13G (F25NWB)	PR
425773	WELL	PR	04/08/2013	GW	045-21063	BENZEL FEDERAL 24-13C (F25NWB)	PR

**General Comment:**

[Facilities on location ID 335104](#)

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

# 17

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 3

Comment: [Chemical units at wellhead](#)

Corrective Action:

Date:

**Venting:**

Yes/No

NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	423618	Type:	WELL	API Number:	045-20779	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	424130	Type:	WELL	API Number:	045-20841	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	424139	Type:	WELL	API Number:	045-20842	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	424191	Type:	WELL	API Number:	045-20843	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	424193	Type:	WELL	API Number:	045-20844	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	424196	Type:	WELL	API Number:	045-20845	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	424201	Type:	WELL	API Number:	045-20846	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	424204	Type:	WELL	API Number:	045-20847	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				

Facility ID:	424206	Type:	WELL	API Number:	045-20848	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424207	Type:	WELL	API Number:	045-20849	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424256	Type:	WELL	API Number:	045-20871	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424260	Type:	WELL	API Number:	045-20873	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424262	Type:	WELL	API Number:	045-20874	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424264	Type:	WELL	API Number:	045-20876	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424265	Type:	WELL	API Number:	045-20877	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424266	Type:	WELL	API Number:	045-20878	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	424267	Type:	WELL	API Number:	045-20879	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	425773	Type:	WELL	API Number:	045-21063	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

## Environmental

### Spill/Remediation:

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Gravel	Pass					
Retention Ponds	Pass					
Waddles	Pass					
Ditches	Pass					
		Gravel	Pass			
		Culverts	Pass			
		Ditches	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT