

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2016

Submitted Date:

10/27/2016

Document Number:

666802681**FIELD INSPECTION FORM**

Loc ID 335321 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266772	WELL	PR	10/09/2003	GW	045-09181	ALP 25-9C (J25)	PR
266773	WELL	PR	10/09/2003	GW	045-09180	ALP 25-16 (J25)	PR
266774	WELL	PR	11/01/2012	GW	045-09179	ALP 25-8C (J25)	PR
266796	WELL	PR	10/12/2003	GW	045-09184	ALP 25-10 (J25)	PR
266797	WELL	PR	06/11/2004	GW	045-09183	ALP 25-9 (J25)	PR
281899	WELL	PR	05/27/2006	GW	045-11567	ALP 25-9D(J25NW)	PR
281901	WELL	PR	05/27/2006	GW	045-11568	ALP 25-8CI (J25NW)	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: [AIRS ID 045-0678-001](#)

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Vertical Heated Separator

# 7

Comment:

Corrective Action:

Date:

Type: Emission Control Device

# 1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 7

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,

Comment: [Centralized battery](#)

Corrective Action:

Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment:		Centralized battery				
Corrective Action:						Date:
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tanak ID	SE GPS	
CONDENSATE	1	500 BBLs	STEEL AST		39.496816,-107.722918	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	266772	Type:	WELL	API Number:	045-09181	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	266773	Type:	WELL	API Number:	045-09180	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	266774	Type:	WELL	API Number:	045-09179	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	266796	Type:	WELL	API Number:	045-09184	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	266797	Type:	WELL	API Number:	045-09183	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	281899	Type:	WELL	API Number:	045-11567	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	281901	Type:	WELL	API Number:	045-11568	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
		Gravel	Pass			
		Culverts	Pass			
Berms	Pass					
		Ditches	Pass			
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT